

ENG FORM 4025-R, MAR 2012

TRANISMITTAI NO

01450 645

(This section will be initiated by the contractor)

☒ THIS IS A NEW TRANSMITTAL
☐ THIS IS A RESUBMITTAL OF
TRANSMITTAL

THIS TRANSMITTAL IS FOR: (Check one)

NO. OF COPIES	CONTRACT REFERENCE		CONTRACTOR REVIEW CODE	VARIATION Enter "Y" if requesting a variation
	SPEC.	DRAWING		

!

[illegible]

I certify that the above submitted items have been reviewed in detail and are correct and in the strict conformance with the contract drawings and specifications except as otherwise stated.

ERIC D. KRAMER

ERD

NAME AND SIGNATURE OF CONTRACTOR

DATE _____

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263017	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351255 JJK				
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032						
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000029087						
7. Transporter 2 Company Name			U.S. EPA ID Number						
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032 Facility's Phone: 973-344-1004			U.S. EPA ID Number NJ0901291105						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
			No.	Type					
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	ES 22	Y	D008		
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information (1) 173266992 - Lead acid bat ERG# 171 Chemtrec CCN4876 THIS #7 A9337X									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Officer's Printed/Typed Name MATHIE CASARSA ON BEHALF OF USEPA			Signature 			Month 2	Day 2	Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:						
	Transporter signature (for exports only):								
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name CALVIN MANLEY		Signature Cal Manley			Month 2	Day 2	Year 18	
	Transporter 2 Printed/Typed Name		Signature			Month	Day	Year	
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 550401b								
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL								
	Manifest Reference Number: U.S. EPA ID Number								
	Facility's Phone:								
	18c. Signature of Alternate Facility (or Generator)						Month 2	Day 2	Year 18
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H110			2.			3.			
4.									
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name Diana MORIAS			Signature Diana Morias			Month 2	Day 2	Year 18	

CLEAN EARTH

Faster, smarter, greener solutions...

GENERATOR USEPA REG 2

MAN. NO. 01835125JJK

TRANSPORTER JSD

VEHICLE ID. 7

DRIVER ON OFF

REMARKS:

81920 LB

07:45 AM 02/02/18

OUT

26880 LB

08:52 AM 02/02/18



55040
WEIGHER

Waste Shipping Checklist

Date: 2, 2, 18

Manifest Document No. 18351255 JJZ

Trucking Company J+N

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers 09-3374

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print: William Zogh

Sign: [Signature]

Date: 2, 2, 18

212976

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0084263817	2. Page 1 of 1	3. Emergency Response Phone 890-424-8300	4. Manifest Tracking Number 018351256 JJK
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		
Generator's Phone: 073-344-2072					
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJRC000020087	
7. Transporter 2 Company Name				U.S. EPA ID Number	
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD091281105	
Facility's Phone: 0733444094					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity
			No.	Type	12. Unit Wt./Vol.
	X	1. RD, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	657 22
		2.			Y
		3.			
		4.			
13. Waste Codes D008					
14. Special Handling Instructions and Additional Information (1) 07302000 - Lead sulfate ERG# 171 Chemtrac CGN4878					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Offor's Printed/Typed Name MATTHE CRAMA in name of USEPA			Signature <i>[Signature]</i>		Month Day Year 2 2 18
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____				
	17. Transporter Acknowledgment of Receipt of Materials				
TRANSPORTER	Transporter 1 Printed/Typed Name JONATHAN LOPEZ		Signature <i>[Signature]</i>		Month Day Year 02 02 18
	Transporter 2 Printed/Typed Name		Signature		Month Day Year
DESIGNATED FACILITY	18. Discrepancy				
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 48800/lbs				
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL				
	Facility's Phone: _____				
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year				
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
1. H110		2.		3.	
				4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
Printed/Typed Name Dora MORIA			Signature <i>[Signature]</i>		Month Day Year 2 2 18

CLEAN EARTH

Faster, smarter, greener solutions...

GENERATOR

USEPA REG

MAN. NO.

01835123JK

TRANSPORTER

J&D

VEHICLE ID.

2

DRIVER ON

OFF

REMARKS:

77720 LB

07:50 AM 02/02/18

28820 LB

08:54 AM 02/02/18

48800
WEIGHER

WEIGH-TRONIX®

Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b) between waste a facility actually received residues, which are residues

2. For rejected loads and residues (i.e., rejected by the generator, rejected by the transporter, or rejected by the facility) cannot be removed from reference the manifest to indicate the original manifest

3. Owners or operators of facilities (i.e., generators, transporters, or facilities) who cannot register with a copy of the manifest

4. Owners or operators of hazardous waste management facilities "differences" to state officials

Item 18b. Alternate Facility (or

Enter the name, address, and phone number of the facility with the generator, to receive the waste. The TSDF may enter the generator's name

Item 18c. Alternate Facility (or

The authorized representative of the alternate facility (or the generator in the event of a returned shipment) must sign and date this field of the form to acknowledge receipt of the fully rejected wastes or residues identified by the initial TSDF.

Item 19. Hazardous Waste Report Management Method Codes

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

RECEIVED PENDING MANIFEST
REVIEW AND QUALITY CONTROL

Waste Shipping Checklist

Date: 21218

Manifest Document No. 18351256 JJK

Trucking Company JJK

Waste Decal Nos. NJ # 02206

Destination: Clean Earth of New Jersey
Kearny, NJ

Truck Nos. 2

Truck License Numbers AS-382 R

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print: Walter Zank

Sign: [Signature]

Date: 21218

212976

3

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 930-424-9300	4. Manifest Tracking Number 018351257 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000029987				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032			U.S. EPA ID Number NJD991291105				
Facility's Phone: 9733444804							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III	1	DT	EST 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173003000 - Lead addition ERG# 171 Chemtrec CCN4878 Tris #7 A8337X							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name MARCEL CRANSA IN BEHALF OF USEPA			Signature <i>[Signature]</i>			Month Day Year 2 2 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Calvin Mantley			Signature <i>[Signature]</i>		Month Day Year 2 2 18	
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name			Signature		Month Day Year	
	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 5322016						
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL			U.S. EPA ID Number			
	Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)					Month Day Year		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Doug MORAN			Signature <i>[Signature]</i>			Month Day Year 2 2 18	

1A



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives, which are residues, which are residues
2. For rejected loads and rejected load (i.e., rejected by the facility cannot be removed from the reference the manifest trace. Indicate the original manifest
3. Owners or operators of facilities (program) who cannot resolve letter with a copy of the Manifest
4. Owners or operators of facilities hazardous waste management differences" to state officials

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSDF may enter the generator

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the full

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **USEPA**MAN. NO. **018351257JJK**TRANSPORTER **IED**VEHICLE ID. **7**

DRIVER ON OFF

REMARKS:


53220
 WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2, 2, 18

Manifest Document No. 18351257 JJK

Trucking Company J+J

Waste Decal Nos. NJ # 02216

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-337X

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓




✓

Shipping Documentation Completed By:

Print: Walter Zales

Sign: [Signature]

Date: 2, 2, 18

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 850-424-8300		4. Manifest Tracking Number 018351258 JJK				
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave. Kearny, NJ 07032 Generator's Phone: 973-344-2072						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave. Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC		U.S. EPA ID Number NJR000028967										
7. Transporter 2 Company Name		U.S. EPA ID Number										
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		U.S. EPA ID Number NJD001291105										
Facility's Phone: 9733444004												
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
						No.	Type					
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III				1	DT	EST 22	Y	D008		
		2.										
		3.										
	4.											
14. Special Handling Instructions and Additional Information (1) 173000000 - Lead and/or Lead Compounds ERG# 171 Chemtrec CCN4876												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offor's Printed/Typed Name Matthew Chandra on BEHALF of USEPA						Signature 		Month 2		Day 2 Year 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____											
	17. Transporter Acknowledgment of Receipt of Materials											
TRANSPORTER	Transporter 1 Printed/Typed Name JONATHAN LOPEZ						Signature 		Month 02		Day 02 Year 18	
	Transporter 2 Printed/Typed Name						Signature		Month		Day Year	
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 50960/L											
	Manifest Reference Number: _____											
	18b. Alternate Facility (or Generator) U.S. EPA ID Number											
	Facility's Phone: _____											
18c. Signature of Alternate Facility (or Generator) Month Day Year												
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)												
1. H110				2.				3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a												
Printed/Typed Name Doug MORAN						Signature 		Month 2		Day 2 Year 18		

/A

IN

Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives and residues, which are residues.
2. For rejected loads and rejected load (i.e., rejected by the facility cannot be removed from the reference the manifest trace. Indicate the original manifest.
3. Owners or operators of a program) who cannot resolve letter with a copy of the Manifest.
4. Owners or operators of a hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSD. TSD may enter the generator.

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the facility.

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.



GENERATOR USEPA REG 2
 MAN. NO. 018357258JK
 TRANSPORTER TSD
 VEHICLE ID. 2
 DRIVER ON OFF
 REMARKS:



50960
 WEIGHER

OUT

Waste Shipping Checklist

Date: 2.2.18

Manifest Document No. 1035125811K

Trucking Company J + J trucks

Truck Nos. 2

Waste Decal Nos. NJ # 02206

Truck License Numbers AS-38212

Clean Earth of New Jersey

Destination: Kearny, NJ

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

Sat / Unsat / N/A

No holes are visible in the shipping container

✓

Previous placarding/ labels removed or defaced

✓

No free standing water

✓

SHIPPING TASKS

No leakage of water / waste material

✓

Container lock mechanism applied

✓

Waste Manifest Completed / Attached

✓

Authorized Manifest Signatures Clearly Written

✓

OFFICE TASKS

Copy for Project Files Completed

✓

Copy for SES Completed

✓

Copy for USACE Completed

✓

Shipping Documentation Completed By:




Print:

Sign:

Date:

2.2.18

212976

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351259 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000020987		
7. Transporter 2 Company Name				U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD001281105		
Facility's Phone: 973-344-4604						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-II	1	DT	EST 22	Y
14. Special Handling Instructions and Additional Information (1) 179033006 - Lead acid bat EPCW 171 Chemtrac CCM4876 <div style="text-align: center; font-size: 1.5em; margin-top: 10px;">1-15 #7 AS337X</div>						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name Maria			Signature 		Month 2	Day 2
					Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____					
	Transporter signature (for exports only): _____					
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name CALVIN MAILEY			Signature 		Month 2
					Year 18	
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 5084 lbs Manifest Reference Number: _____					
18b. Alternate Facility (or Generator)			U.S. EPA ID Number			
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)					Month	Day
					Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Doug MORRIS			Signature 		Month 2	Day 18
					Year 18	



Item 18 Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives, which are residues, which are residues.
2. For rejected loads and rejected load (i.e., rejected by the facility cannot be removed from the facility reference the manifest line. Indicate the original manifest.
3. Owners or operators of facilities (program) who cannot resolve the matter with a copy of the Manifest.
4. Owners or operators of facilities hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone number with the generator, to receive the waste. If the TSD facility enter the generator's name.

Item 18c. Alternate Facility (or Generator)

The authorized representative must acknowledge receipt of the full amount of the waste.

Item 19 Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20 Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **USEPA**
 MAN. NO. **018357259JJK**
 TRANSPORTER **JSD**
 VEHICLE ID. **7**
 DRIVER ON OFF
 REMARKS:



50840
 WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2 12 18

Manifest Document No. 18351259JJk

Trucking Company J+J

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS3374

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print: Walter Zepher

Sign: [Signature]

Date: 2 2 18

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 950-424-9300	4. Manifest Tracking Number 018351260 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2072								
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR009029987				
7. Transporter 2 Company Name				U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD061291105				
Facility's Phone: 8733444094								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
	X	1. RG, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	657 22	Y	D008	
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information (1) 17300000 - Lead acid batteries EPA08 171 Chemtrac CCN4878								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offoror's Printed/Typed Name MARINA CRANNA IN BEHALF OF USEPA			Signature <i>[Signature]</i>			Month	Day Year	
						2	2 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
	Transporter signature (for exports only): _____							
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name JONATHAN LOPEZ			Signature <i>[Signature]</i>			Month	Day Year
						02	02 18	
Transporter 2 Printed/Typed Name			Signature			Month	Day Year	
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Rec'd 5066016							
	18b. Alternate Facility (or Generator)					Manifest Reference Number:		U.S. EPA ID Number
	Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)							Month	Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Doug MORIAN			Signature <i>[Signature]</i>			Month	Day Year	
						2	2 18	



Item 18. Discrepancy

Item 18a. Discrepancy Indicator

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually received residues, which are residues
2. For rejected loads and rejected load (i.e., rejected by the facility cannot be removed from the facility reference the manifest to indicate the original manifest
3. Owners or operators of facility (program) who cannot receive letter with a copy of the Manifest
4. Owners or operators of facility hazardous waste management differences" to state officials

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSDf may enter the generator

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the facility

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **UJSPA**MAN. NO. **018357260JK**TRANSPORTER **JSD**VEHICLE ID. **2**

DRIVER ON OFF

REMARKS:


50660
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2 1 21/8

Manifest Document No. 01835126000K

Trucking Company J + D

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS-382K

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

Sat / Unsat / N/A

No holes are visible in the shipping container

✓

Previous placarding/ labels removed or defaced

✓

No free standing water

✓

SHIPPING TASKS

No leakage of water / waste material

✓

Container lock mechanism applied

✓

Waste Manifest Completed / Attached

✓

Authorized Manifest Signatures Clearly Written

✓

OFFICE TASKS

Copy for Project Files Completed

✓

Copy for SES Completed

✓

Copy for USACE Completed

✓




Shipping Documentation Completed By:

Print: William Z...

Sign: [Signature]

Date: 2 1 21/8

212976

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351261 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2072								
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000028887					
7. Transporter 2 Company Name			U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD061281105					
Facility's Phone: 973-444-0094								
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) 1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
			1	DT	EST 22	Y		D008
14. Special Handling Instructions and Additional Information (1) 17000000 - Liquid and Gas EPCW 171 Chemtrac CCM4878 THIS IS 7 AS337X								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Matthew C. Mankin on Behalf of USEPA			Signature 		Month 2	Day 2	Year 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name CALVIN MANLEY			Signature 		Month 2	Day 2	Year 18	
Transporter 2 Printed/Typed Name			Signature		Month	Day	Year	
18. Discrepancy								
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Reid AS32061								
18b. Alternate Facility (or Generator)			Manifest Reference Number: U.S. EPA ID Number					
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator)						Month	Day	Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Doug Morison			Signature 		Month 2	Day 2	Year 18	

IN

CLEANEARTH

Faster, smarter, greener solutions...

GENERATOR **USEPA**

MAN. NO. **01835126 JJK**

TRANSPORTER **J&D**

VEHICLE ID. **7**

DRIVER ON OFF

REMARKS:

82140 LB

10:10 AM 02/02/18

OUT

26820 LB

10:42 AM 02/02/18

55320
WEIGHER

WEIGH-TRONIX®

Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between waste a facility actually received residues, which are rejected

2. For rejected loads and residues, rejected by the facility, cannot be removed from reference the manifest to indicate the original manifest

3. Owners or operators of (or program) who cannot receive letter with a copy of the

4. Owners or operators of (or hazardous waste management differences" to state official

Item 18b. Alternate Facility (or

Enter the name, address, phone number, and fax number of the generator, to receive TSDF may enter the generator

Item 18c. Alternate Facility (or

The authorized representative of the alternate facility (or the generator in the event of a returned shipment) must sign and date this field of the form to acknowledge receipt of the fully rejected wastes or residues identified by the initial TSDF.

Item 19. Hazardous Waste Report Management Method Codes

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

RECEIVED PENDING MANIFEST
REVIEW AND QUALITY CONTROL

Waste Shipping Checklist

Date: 2.2.18

Manifest Document No. 18351261JJK

Trucking Company JFD

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS 3374

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓
✓
✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓
✓
✓
✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓
✓
✓

Shipping Documentation Completed By:

Print: Walter J. Felt

Sign: WJF

Date: 2.2.18

212976

UNIFORM HAZARDOUS WASTE MANIFEST		4. Generator ID Number NJD064263017	2. Page 1 of 1	3. Emergency Response Phone 856-424-8300	4. Manifest Tracking Number 018351262 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072				U.S. EPA ID Number NJR000020067			
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of Newark, Jersey 105 Jacobus Ave Kearny NJ 07032				U.S. EPA ID Number NJD061291105			
Facility's Phone: 9733444094							
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
		No.	Type				
X	1. RD, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1	DT	EST 22	Y	D008	
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information (1) 172000000 - Lead collection ERCB 171 Chemicals CCN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's Offeror's Printed/Typed Name Manuel Chavez of Bureau of US EPA				Signature <i>[Signature]</i>		Month Day Year 2 2 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name JONATHAN LOPEZ				Signature <i>[Signature]</i>		Month Day Year 02 02 18	
Transporter 2 Printed/Typed Name				Signature		Month Day Year	
18. Discrepancy							
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 52840lb							
18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number: _____			
Facility's Phone: _____							
18c. Signature of Alternate Facility (or Generator) _____ Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Rua Morales				Signature <i>[Signature]</i>		Month Day Year 2 2 18	



Item 18 Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between waste a facility actually received residues, which are residues
2. For rejected loads and re-load (i.e., rejected by the cannot be removed from reference the manifest to indicate the original manifest
3. Owners or operators of facility (program) who cannot resubmit letter with a copy of the Manifest
4. Owners or operators of facility hazardous waste management differences" to state officials

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSDf may enter the general

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the facility

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDf) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDf.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDf as offeror of the shipment.

GENERATOR **USEPA**
 MAN. NO. **018357262JTK**
 TRANSPORTER **USD**
 VEHICLE ID. **2**
 DRIVER ON OFF
 REMARKS:



52840
 WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 212110

Manifest Document No. 18351262JJR

Trucking Company J+H trucks

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS 382R

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓
✓
✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓
✓
✓
✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓
✓
✓

Shipping Documentation Completed By:

Print: William Zick

Sign: [Signature]

Date: 212110

212976

9

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0001291105	2. Page 1 of 1	3. Emergency Response Phone NJ0001291105	4. Manifest Tracking Number 018351263 JJK
5. Generator's Name and Mailing Address USEPA Region 7 77 Jacobus Ave. Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 7 77 Jacobus Ave. Kearny, NJ 07032		
Generator's Phone: 973-444-604			U.S. EPA ID Number NJR000029967		
6. Transporter 1 Company Name			U.S. EPA ID Number		
7. Transporter 2 Company Name			U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny, NJ 07032			U.S. EPA ID Number NJ0091291105		
Facility's Phone: 973-444-604					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity
			No.	Type	12. Unit Wt./Vol.
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22
		2.			Y
		3.			
		4.			
13. Waste Codes D008					
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chemtrac CCN4876 TIN 9 7 A8337X					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Officer's Printed/Typed Name MARTIN MANLEY on Behalf of USSFA					Signature [Signature] Month Day Year 12 2 18
INTL	16. International Shipments: <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____				
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Calvin Manley Signature Cal Manley Month Day Year 12 2 18 Transporter 2 Printed/Typed Name _____ Signature _____ Month Day Year _____				
DESIGNATED FACILITY	18. Discrepancy				
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Reid 51500lb				
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL Facility's Phone: _____ Manifest Reference Number: _____ U.S. EPA ID Number _____				
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____				
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. 3. 4.					
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Doug MORITZ Signature [Signature] Month Day Year 12 2 18					



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives, which are residues, which are residues
2. For rejected loads and reloaded (i.e., rejected by the cannot be removed from reference the manifest to indicate the original manifest
3. Owners or operators of facilities (program) who cannot register letter with a copy of the Manifest
4. Owners or operators of facilities hazardous waste management differences" to state officials

Item 18b. Alternate Facility (or)

Enter the name, address, phone with the generator, to receive TSDF may enter the general

Item 18c. Alternate Facility (or)

The authorized representative acknowledge receipt of the

Item 19. Hazardous Waste Rep

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **UJEPH**MAN. NO. **018351263JTK**TRANSPORTER **JSD**VEHICLE ID. **7**

DRIVER ON OFF

REMARKS:



51500
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 21 2, 18

Manifest Document No. 18351263JJk

Trucking Company J + D

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-337X

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓




✓

Shipping Documentation Completed By:

Print: Walter Taylor

Sign: Walter Taylor

Date: 21 2, 18

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 990-424-8300	4. Manifest Tracking Number 018351264 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2972								
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000029967				
7. Transporter 2 Company Name				U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD091291105				
Facility's Phone: 9733444094								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RO, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III		1	DT	EST 22	Y	D008
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information (1) 173023000 - Lead solution ERG 171 Chemtrac CGN4878								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name MARCO CRANER ON BEHALF OF USEPA				Signature 		Month Day Year 2 2 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
	17. Transporter Acknowledgment of Receipt of Materials							
TRANSPORTER	Transporter 1 Printed/Typed Name JONATHAN LOPEZ				Signature 		Month Day Year 02 02 18	
	Transporter 2 Printed/Typed Name				Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 49760/b3							
	18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number _____			
	Facility's Phone: _____							
	18c. Signature of Alternate Facility (or Generator)				Month Day Year			
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110			2.			3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name DAUG KURHAN				Signature 		Month Day Year 2 2 18		



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually received and residues, which are residues.
2. For rejected loads and rejected load (i.e., rejected by the cannot be removed from reference the manifest (to indicate the original manifest).
3. Owners or operators of facilities (program) who cannot resolve letter with a copy of the letter.
4. Owners or operators of facilities hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or)

Enter the name, address, phone with the generator, to receive TSDF may enter the generator.

Item 18c. Alternate Facility (or)

The authorized representative acknowledge receipt of the facility.

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **USEPA**MAN. NO. **018351264JJK**TRANSPORTER **JHD**VEHICLE ID. **2**

DRIVER ON OFF

REMARKS:



707-0 LB

11:43 AM 02/02/19

IN

OUT

707-0 LB

11:43 AM 02/02/19

49760
WEIGHER

Waste Shipping Checklist

Date: 21 2 18

Manifest Document No. 18351264JJK

Trucking Company J + J

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS 38212

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓




Shipping Documentation Completed By:

Print: William Zepher

Sign: [Signature]

Date: 21 2 18

212976

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263217	2. Page 1 of 1	3. Emergency Response Phone 800-424-6300	4. Manifest Tracking Number 018351265 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000020007		
7. Transporter 2 Company Name				U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD001291105		
Facility's Phone: 9733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		No.	Type			
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1	DT	Est 22	Y	D008
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information (1) 17000000 - Long distance HRCW 177 Chemical CCN4878 1515-1-148337X						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name Matthew Chasen on behalf of USEPA				Signature 		Month Day Year 2 2 18
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Cal Manley				Signature 		Month Day Year 2 2 18
Transporter 2 Printed/Typed Name				Signature		Month Day Year
18. Discrepancy						
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 52120/60						
18b. Alternate Facility (or Generator)				Manifest Reference Number: _____		
Facility's Phone:				U.S. EPA ID Number		
18c. Signature of Alternate Facility (or Generator)						Month Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Donna Morahan				Signature 		Month Day Year 2 2 18

IN



Item 18, Discrepancy

Item 18a, Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b) between the waste a facility actually receives, which are residues,
2. For rejected loads and residues (i.e., rejected by the facility cannot be removed from the reference the manifest and indicate the original manifest
3. Owners or operators of facilities (program) who cannot resolve letter with a copy of the Manifest
4. Owners or operators of facilities hazardous waste management differences to state official

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

Item 18b, Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSDf may enter the generator

Item 18c, Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the full

Item 19, Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method Code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20, Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.



52120
WEIGHER

OUT

Waste Shipping Checklist

Date: 212118

Manifest Document No. 18351265 JJK

Trucking Company J+D

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-337X

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓
✓
✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓
✓
✓
✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓
✓
✓

Shipping Documentation Completed By:

Print: William Zaff

Sign: [Signature]

Date: 212118

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351266 JJK		
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC		02 AS-382R		U.S. EPA ID Number NJR000020067						
7. Transporter 2 Company Name				U.S. EPA ID Number						
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD081201105						
Facility's Phone: 9733444004										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	X	1. RO, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III			1		DT	EST 22	Y	D008
		2.								
		3.								
		4.								
14. Special Handling Instructions and Additional Information (1) 173000030 - Lead and Arsenic ENCL 171 Chemtrac CCN4878										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generator's/Offor's Printed/Typed Name MARCUS CHAMBERLAIN ON BEHALF OF USPA					Signature 		Month Day Year 2 2 18			
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____									
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name JONATHAN LOPEZ Signature Month Day Year 02 02 18 Transporter 2 Printed/Typed Name _____ Signature _____ Month Day Year _____									
DESIGNATED FACILITY	18. Discrepancy									
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Red 53360/lb									
	18b. Alternate Facility (or Generator)						U.S. EPA ID Number			
	Facility's Phone: _____									
18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____										
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)										
1. H110		2.		3.		4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a										
Printed/Typed Name DONG MURIAS					Signature		Month Day Year 2 2 18			



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between waste a facility actually received residues, which are residues
2. For rejected loads and rejected load (i.e., rejected by the cannot be removed from reference the manifest to indicate the original manifest
3. Owners or operators of facility (program) who cannot register letter with a copy of the facility
4. Owners or operators of facility hazardous waste management differences" to state official

Item 18b. Alternate Facility (or

Enter the name, address, phone with the generator, to receive TSDF may enter the generator

Item 18c. Alternate Facility (or

The authorized representative acknowledge receipt of the

Item 19. Hazardous Waste Rejection

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR **USEPA**
 MAN. NO. **018351266JTX**
 TRANSPORTER **JSD**
 VEHICLE ID. **2**
 DRIVER ON OFF
 REMARKS:



53360
 WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2, 2, 18

Manifest Document No. 18351266JJK

Trucking Company J+J

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS-382R

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓
✓
✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓
✓
✓
✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓
✓
✓

Shipping Documentation Completed By:

Print: Walter Zylke

Sign: [Signature]

Date: 2, 2, 18

212976

13

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263817	2. Page 1 of 1	3. Emergency Response Phone 850-424-8300	4. Manifest Tracking Number 018351267 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 073-344-2872						
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJ000028887		
7. Transporter 2 Company Name				U.S. EPA ID Number		
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032				U.S. EPA ID Number NJ0001261105		
Facility's Phone: 8733444084						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D006), 9, PG-III	1	DT	657 22	Y
14. Special Handling Instructions and Additional Information (1) 173063517 - Lead contamination ER00177 Chemtrac CCN4878 TRK #7 A8337 X						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name MATTHEW CHAMBERLAIN ON BEHALF OF USEPA			Signature 		Month 2	Day 2
					Year 18	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____					
	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name Calvin Manley			Signature 		Month 2
	Transporter 2 Printed/Typed Name			Signature		Day 2
						Year 18
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 55680 lbs					
	Manifest Reference Number: _____					
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____					
	Facility's Phone: _____					
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____					
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
	1. H110		2. _____		3. _____	
					4. _____	
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
	Printed/Typed Name Joseph Moran			Signature 		Month 2
						Day 2
						Year 18



Item 18a. Discrepancy Indicatl

Item 18a. Discrepancy Indicatl

1. The authorized representative described on the Manifest and 265.72(b) between waste a facility actually receives residues, which are residues.
2. For rejected loads and rejected load (i.e., rejected by the facility) cannot be removed from reference the manifest. Indicate the original manifest.
3. Owners or operators of the program) who cannot receive letter with a copy of the manifest.
4. Owners or operators of hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or)

Enter the name, address, and phone number of the person you wish to contact, along with the generator, to receive the TSD Form. TSD may enter the generator

Item 18c. Alternate Facility (a)

The authorized representative
acknowledge receipt of the

Item 19. Hazardous Waste Ri



Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR WEPA
MAN. NO. 018351267JJK
TRANSPORTER RSD
VEHICLE ID. 7
DRIVER ON OFF
REMARKS:

IN

OUT

01:46 PM 12/12/19

20260-11

55680
WEIGHER

Waste Shipping Checklist

Date: 2 12 11

Manifest Document No. 18351267 JJK

Trucking Company J + D

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-3374

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:




Print: Mike Zales

Sign: [Signature]

Date: 2 12 11

212976

14

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD004263917	2. Page 1 of 1	3. Emergency Response Phone 878-424-8300	4. Manifest Tracking Number 018351268 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 873-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000020067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032			U.S. EPA ID Number NJD001291105			
Facility's Phone: 8733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
		No.	Type			
X	1. RQ, NA3077, Hazardous waste, solid, n.o.e. (D008), 9, PG-II	1	DT	22 EST	Y	D008
14. Special Handling Instructions and Additional Information (1) 17306003 - Liquid spill Area EROP 171 Chemtrac CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name MARIE CARMAN ON BEHALF OF USEPA		Signature 		Month Day Year 2 2 18		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name JONATHAN LOPEZ		Signature 		Month Day Year 02 02 18		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 53680L						
18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number		
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)						Month Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name MARIE CARMAN		Signature 		Month Day Year 2 2 18		



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives, which are residues,
2. For rejected loads and re-load (i.e., rejected by the cannot be removed from reference the manifest trace. Indicate the original manifest.
3. Owners or operators of the program) who cannot resubmit letter with a copy of the Manifest.
4. Owners or operators of the hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSD. TSD may enter the generator.

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the full.

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR USEPA
 MAN. NO. 01835126804
 TRANSPORTER USD
 VEHICLE ID 2
 DRIVER ON OFF
 REMARKS:



53680
 WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2 12 118

Manifest Document No. 1835126201K

Trucking Company JFI

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS-38212

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓




✓

Shipping Documentation Completed By:

Print: Walter Zylke

Sign: WZ

Date: 2 12 118

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD004263817	2. Page 1 of 1	3. Emergency Response Phone 890-434-8300	4. Manifest Tracking Number 018351269 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000020007			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 185 Jacobus Ave. Keamy NJ 07032				U.S. EPA ID Number NJD001201105			
Facility's Phone: 973-344-4004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y	D008
14. Special Handling Instructions and Additional Information (1) 173303838 - Lead paint ER01-171 Chemical: CCN4878 THK #7 A8337X							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Matthew Cranga ON BEHALF OF USEPA			Signature 		Month 2	Day 2	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Calvin Manley			Signature 		Month 2	Day 2	
Transporter 2 Printed/Typed Name			Signature		Month	Day	
18. Discrepancy							
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 55300lbs							
18b. Alternate Facility (or Generator)					Manifest Reference Number: _____ U.S. EPA ID Number		
Facility's Phone: _____							
18c. Signature of Alternate Facility (or Generator)					Month	Day	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Doug MORIAI			Signature 		Month 2	Day 2	



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually received residues, which are residues
2. For rejected loads and re-load (i.e., rejected by the facility cannot be removed from reference the manifest to indicate the original manifest
3. Owners or operators of the program) who cannot receive letter with a copy of the letter
4. Owners or operators of the hazardous waste management differences" to state official

Item 18b. Alternate Facility (or

Enter the name, address, phone with the generator, to receive (SD) may enter the generator

Item 18c. Alternate Facility (or

The authorized representative acknowledge receipt of the

Item 19. Hazardous Waste Rejection

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR 455PAMAN. NO. 01835126TRANSPORTED RTSDVEHICLE ID. 7

DRIVER ON OFF

REMARKS:



55300
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2 1 2 1 1 8

Manifest Document No. 18351269JVK

Trucking Company J+H

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-337X

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓
✓
✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓
✓
✓
✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed




✓
✓
✓

Shipping Documentation Completed By:

Print: Walter Zuber

Sign: [Signature]

Date: 2 1 2 1 1 8

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817	2. Page 1 of 1	3. Emergency Response Phone 878-424-8300	4. Manifest Tracking Number 018351270 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJF000020987				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD081201105				
Facility's Phone: 973-344-4004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173083032 - Load on 4000 ERG# 171 Chemtrac CCN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name MATTHEW CRAMER ON BEHALF OF USPOB		Signature 		Month 2	Day 2	Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name JONATHAN LOPEZ		Signature 		Month 02	Day 02	Year 18
	Transporter 2 Printed/Typed Name		Signature		Month	Day	Year
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Reid 53340/lbs						
	18b. Alternate Facility (or Generator)				U.S. EPA ID Number		
	Facility's Phone:						
	18c. Signature of Alternate Facility (or Generator)				Month	Day	Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Donna MURIAS		Signature 		Month 2	Day 2	Year 18	



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually received and residues, which are residues.
2. For rejected loads and residues (i.e., rejected by the facility cannot be removed from a reference the manifest trace. Indicate the original manifest.
3. Owners or operators of facilities (program) who cannot receive letter with a copy of the Manifest.
4. Owners or operators of facilities hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone number with the generator, to receive TSDF may enter the generator's name.

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the waste.

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR USE PA

MAN. NO. 018351270JK

TRANSPORTER JSD

VEHICLE ID. 2

DRIVER ON OFF

REMARKS:



52340
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 21 2 18

Manifest Document No. 18351270J1K

Trucking Company J + J

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS 38-2K

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print:

Walter Zepher

Date:




21 2 18

Sign:

[Signature]

212976

17

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 970-424-8300	4. Manifest Tracking Number 018351271 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000028887			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD001281105			
Facility's Phone: 973-344-4004							
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
		No.	Type				
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y	D008	
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information (1) 173033035 - Lead and lead compounds ERG 171 Chemtrac CCN4878 1515-7-18337X							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name MATTHEW CRAMER ON BEHALF OF USEPA				Signature 		Month Day Year 2 2 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name CARL MALLEY				Signature 		Month Day Year 2 2 18	
Transporter 2 Printed/Typed Name				Signature		Month Day Year	
18. Discrepancy							
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 53640lb							
18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number			
Facility's Phone: _____							
18c. Signature of Alternate Facility (or Generator)						Month Day Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name DOUG MORIN				Signature 		Month Day Year 2 2 18	

**CLEANGARTH**

Faster, smarter, greener solutions...

Item 18. Discrepancy**Item 18a. Discrepancy Indication**

1. The authorized representative described on the Manifest and 265.72(b)) between waste a facility actually received residues, which are residues.
2. For rejected loads and rejected load (i.e., rejected by the cannot be removed from reference the manifest (reference the original manifest). Indicate the original manifest.
3. Owners or operators of facility (program) who cannot receive letter with a copy of the Manifest.
4. Owners or operators of facility hazardous waste management differences" to state official.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSDf may enter the general

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the facility

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR

USEP A

MAN. NO.

01835127JSTC

TRANSPORTER

JSD

VEHICLE ID.

7

DRIVER ON

OFF

REMARKS:

IN

OUT

WEIGH-TRONIX®

01/04 PM 02:02/19

53640

WEIGHER

Waste Shipping Checklist

Date: 2, 2, 10

Manifest Document No. 18351271JJH

Trucking Company J + J

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS-3374

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print: Walter Zady

Sign: WZ

Date: 2, 2, 10

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263517	2. Page 1 of 1	3. Emergency Response Phone 800-424-9310	4. Manifest Tracking Number 018351272 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000020867				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032 Facility's Phone: 9733444094			U.S. EPA ID Number NJ0391291105				
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1 DT		65+ 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173083035 - Lead and Lead ERGL 171 Chemtrec CGN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generators/Offeror's Printed/Typed Name MARTIN CRAMER in name of USEPA		Signature [Signature]			Month Day Year 2 2 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:				
	Transporter signature (for exports only):						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name JONATHAN LOPEZ		Signature Jonathan Lopez		Month Day Year 10 02 18		
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy							
18a. Discrepancy Indication Space 18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 51180161							
18b. Alternate Facility (or Generator)			Manifest Reference Number: U.S. EPA ID Number				
18c. Signature of Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name MORIAS		Signature [Signature]			Month Day Year 2 2 18		



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually received and residues, which are rejected.
2. For rejected loads and residues (i.e., rejected by the facility cannot be removed from the reference the manifest and indicate the original manifest.
3. Owners or operators of a facility (program) who cannot register with a copy of the Manifest.
4. Owners or operators of a facility hazardous waste management differences" to state official.

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone number with the generator, to receive the waste. If the TSDf may enter the generator.

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the waste.

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDf) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDf.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDf as offeror of the shipment.

GENERATOR USEPA

MAN. NO. 018351272JR

TRANSPORTER JFD

VEHICLE ID. 2

DRIVER ON OFF

REMARKS:



51180
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 21 21 18

Manifest Document No. 10351272001

Trucking Company J+J

Waste Decal Nos. NJ # 02206

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 2

Truck License Numbers AS-382K

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓

Shipping Documentation Completed By:

Print: William Zuply

Sign: [Signature]

Date: 21 2 18

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351273 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
6. Transporter 1 Company Name J & D TRUCKING INC		U.S. EPA ID Number NJR0000020967					
7. Transporter 2 Company Name		U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032 Facility's Phone: 9733444004		U.S. EPA ID Number NJ0991281106					
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III		1 DT		657 22	Y	D008
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead acid/baz ERG# 171 Chemtrec CCN4876 Tris #7 A8337x							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Matthew Cramer on Behalf of USEPA			Signature [Signature]			Month Day Year 2 2 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:							
17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Signature Month Day Year Calvin Manley Calvin Manley 2 2 18 Transporter 2 Printed/Typed Name Signature Month Day Year							
18. Discrepancy 18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 536206 Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. 3. 4.							
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature Month Day Year Doug MORAN Doug Moran 2 2 18							



Item 18. Discrepancy

Item 18a. Discrepancy Indication

1. The authorized representative described on the Manifest and 265.72(b)) between the waste a facility actually receives and residues, which are residues.
2. For rejected loads and reloaded (i.e., rejected by the cannot be removed from reference the manifest to indicate the original manifest).
3. Owners or operators of facilities (program) who cannot register with a copy of the Manifest.
4. Owners or operators of facilities hazardous waste management differences" to state officials.

Item 18b. Alternate Facility (or Location)

Enter the name, address, phone with the generator, to receive TSDR may enter the general

Item 18c. Alternate Facility (or Location)

The authorized representative acknowledge receipt of the facility

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR USEPAMAN. NO. 0183512300KTRANSPORTER USDVEHICLE ID. 7

DRIVER ON OFF

REMARKS:



50000 LB

01-30 PM 02/02/19

IN

OUT

20040 LB

02-00 PM 02/02/19

53620
WEIGHER

Waste Shipping Checklist

Date: 2, 2, 18

Manifest Document No. 18351273JJR

Trucking Company JTD

Waste Decal Nos. NJ # 02210

Clean Earth of New Jersey

Destination: Kearny, NJ

Truck Nos. 7

Truck License Numbers AS 337X

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

Sat / Unsat / N/A

No holes are visible in the shipping container

✓

Previous placarding/ labels removed or defaced

✓

No free standing water

✓

SHIPPING TASKS

No leakage of water / waste material

✓

Container lock mechanism applied

✓

Waste Manifest Completed / Attached

✓

Authorized Manifest Signatures Clearly Written

✓

OFFICE TASKS

Copy for Project Files Completed

✓

Copy for SES Completed

✓

Copy for USACE Completed




✓

Shipping Documentation Completed By:

Print: William Zuck

Sign: [Signature]

Date: 2, 2, 18

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351274 JJK	
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			
6. Transporter 1 Company Name J & D TRUCKING INC		Generator's Phone: 073-344-2972		U.S. EPA ID Number NJR000020067					
7. Transporter 2 Company Name				U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032		Facility's Phone: 973-444-0004		U.S. EPA ID Number NJD881281105					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
					No.	Type			
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III			1	DT	EST 22	Y	D008
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information (1) 973062835 - Lead acid/batt EROM 171 Chemrec CCN4876									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offoror's Printed/Typed Name MARINE CRANSA ON BEHALF OF USPA					Signature 		Month Day Year 2 2 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____								
	17. Transporter Acknowledgment of Receipt of Materials								
TRANSPORTER	Transporter 1 Printed/Typed Name JONATHAN LOPEZ				Signature 		Month Day Year 02 02 18		
	Transporter 2 Printed/Typed Name				Signature		Month Day Year		
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 55/20/6								
	18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number: _____				
	Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator)				Month Day Year				
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H110		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name JOAQUIN MORIAS					Signature 		Month Day Year 2 2 18		



Item 18. Discrepancy

Item 18a. Discrepancy Indicator

1. The authorized representative described on the Manifest and 265.72(b) between the waste a facility actually received residues, which are residues
2. For rejected loads and residues (i.e., rejected by the facility cannot be removed from a reference the manifest trailer. Indicate the original manifest
3. Owners or operators of facilities (program) who cannot receive letter with a copy of the Manifest
4. Owners or operators of facilities hazardous waste management differences" to state officials

Item 18b. Alternate Facility (or Generator)

Enter the name, address, phone with the generator, to receive TSD. TSD may enter the general

Item 18c. Alternate Facility (or Generator)

The authorized representative acknowledge receipt of the facility

Item 19. Hazardous Waste Report

Enter the most appropriate Hazardous Waste Report Management Method code for each waste listed in Item 9. The Hazardous Waste Report Management Method code is to be entered by the first treatment, storage, or disposal facility (TSDF) that receives the waste and is the code that best describes the way in which the waste is to be managed when received by the TSDF.

Item 20. Designated Facility Owner or Operator Certification of Receipt (Except As Noted in Item 18a)

Enter the name of the person receiving the waste on behalf of the owner or operator of the facility. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date of receipt or rejection where indicated. Since the Facility Certification acknowledges receipt of the waste except as noted in the Discrepancy Space in Item 18a, the certification should be signed for both waste receipt and waste rejection, with the rejection being noted and described in the space provided in Item 18a. Fully rejected wastes may be forwarded or returned using Item 18b after consultation with the generator. Enter the name of the person accepting the waste on behalf of the owner or operator of the alternate facility or the original generator. That person must acknowledge receipt or rejection of the waste described on the Manifest by signing and entering the date they received or rejected the waste in Item 18c. Partially rejected wastes and residues must be re-shipped under a new manifest, to be initiated and signed by the rejecting TSDF as offeror of the shipment.

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:



55120
WEIGHER

IN

OUT

Waste Shipping Checklist

Date: 2, 2, 18

Manifest Document No. 10351274JK

Trucking Company J+I

Waste Decal Nos. NJ # 02206

Destination: Clean Earth of New Jersey
Kearny, NJ

Truck Nos. 2

Truck License Numbers 75-382K

Waste Type: Lead Soil / Haz

No weight scale onsite

PRE-LOADING TASKS

No holes are visible in the shipping container

Previous placarding/ labels removed or defaced

No free standing water

Sat / Unsat / N/A

✓

✓

✓

SHIPPING TASKS

No leakage of water / waste material

Container lock mechanism applied

Waste Manifest Completed / Attached

Authorized Manifest Signatures Clearly Written

✓

✓

✓

✓

OFFICE TASKS

Copy for Project Files Completed

Copy for SES Completed

Copy for USACE Completed

✓

✓

✓




Shipping Documentation Completed By:

Print: Mark Zupis

Sign: [Signature]

Date: 2, 2, 18

213137

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351275 JJK				
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032							
Generator's Phone: 973-344-2072									
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000029967					
7. Transporter 2 Company Name				U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD991291105					
Facility's Phone: 0733444004									
9a. HM	X	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
		1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III		1	DT	Est 22	Y	D008	
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chemtrec CCN4876 <div style="text-align: center; font-size: 1.5em; margin-top: 10px;">TRANS*12 AT904H</div>									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(e) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Officer's Printed/Typed Name Matthew Casanovi on Behalf of USEPA					Signature 		Month Day Year 12/5/18		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:									
17. Transporter Acknowledgment of Receipt of Materials									
Transporter 1 Printed/Typed Name CABIN MANLEY					Signature 		Month Day Year 12/5/18		
Transporter 2 Printed/Typed Name					Signature		Month Day Year		
18. Discrepancy									
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
Manifest Reference Number:									
18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number									
Facility's Phone:									
18c. Signature of Alternate Facility (or Generator) Month Day Year									
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H110		2.		3.		4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a									
Printed/Typed Name Bernice Mills					Signature 		Month Day Year 12/5/18		



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:



IN

81380 LB

07:32 AM 02/05/18

OUT

26820 LB






09:21 AM 02/05/18

54560
WEIGHER

918127

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351276 JJK
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		
Generator's Phone: 973-344-2072					
6. Transporter 1 Company Name J & D TRUCKING INC #19 AT899H no				U.S. EPA ID Number NJR000029067	
7. Transporter 2 Company Name				U.S. EPA ID Number	
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD991291105	
Facility's Phone: 973344-4004					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity
	X	1. RO, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1 1 DT		657 22
		2.			Y
		3.			
		4.			
13. Waste Codes D008					
14. Special Handling Instructions and Additional Information (1) 173083938 - Load soil/Haz ERG# 171 Chemtrec CCN4876					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Officer's Printed/Typed Name Matthew Charnick on Behalf of USEPA				Signature  Month Day Year 12 5 18	
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____				
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Wayne Hantman Signature  Month Day Year 12 5 18 Transporter 2 Printed/Typed Name Signature Month Day Year				
DESIGNATED FACILITY	18. Discrepancy 18a. Discrepancy Indication Spec <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection  Manifest Reference Number: _____				
	18b. Alternate Facility (or Generator) Facility's Phone: _____ U.S. EPA ID Number: _____				
	18c. Signature of Alternate Facility (or Generator)  Month Day Year				
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. 3. 4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a Printed/Typed Name Bernice Mills Signature  Month Day Year 12 5 18					



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

77880 LB

07:55 AM 02/05/18

OUT

27000 LB

09:24 AM 02/05/18

WEIGH-TRONIX®



50880

WEIGHER

2B139

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351277 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD991291105			
Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt/Vol.	13. Waste Codes
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III	1	DT	Est 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chemtrac CGN4876 THAT 904H							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Officer's Printed/Typed Name MATTHEW CASARSA on behalf of USEPA				Signature 		Month Day Year 12/5/18	
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name CATHY MANTLEY				Signature Cathy Mantley		Month Day Year 12/5/18
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name				Signature		Month Day Year
	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL						
	Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Bernice Mills				Signature 		Month Day Year 12/5/18	



IN

GENERATOR *USPA*
MAN. NO. *018351377 JH*

75300 LB

TRANSPORTER *JH*
VEHICLE ID. *B*

09:35 AM 02/05/18

DRIVER ON OFF

OUT

REMARKS:

26840 LB

09:50 AM 02/05/18



49660
WEIGHER

2/13/99

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351278 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NJ		U.S. EPA ID Number NJR000029067				
7. Transporter 2 Company Name		U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		U.S. EPA ID Number NJD991291105				
Facility's Phone: 9733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III		1	DT	Est 22	Y
	2.					
	3.					
4.						
13. Waste Codes D008						
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chamtrac CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offoror's Printed/Typed Name Matthew Ciganga on Behalf of USEPA		Signature 		Month Day Year 12/5/18		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Maya HARTMAN		Signature 		Month Day Year 12/5/18		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space		<input checked="" type="checkbox"/> Quantity	<input type="checkbox"/> Type	<input type="checkbox"/> Residue	<input type="checkbox"/> Partial Rejection	<input type="checkbox"/> Full Rejection
Rec'd 49360 lbs		Manifest Reference Number:				
18b. Alternate Facility (or Generator)		U.S. EPA ID Number				
Facility's Phone:		RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL				
18c. Signature of Alternate Facility (or Generator)		Month Day Year				
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.	H110	2.		3.		4.
20. Designated Facility Owner or Operator. Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a						
Printed/Typed Name Doug MORIAS		Signature 		Month Day Year 12/5/18		

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

76040 LB

09:46 AM 02/05/18

OUT

26680 LB

09:59 AM 02/05/18

49360
WEIGHER



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351279 JJK				
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				
Generator's Phone: 973-344-2072		6. Transporter 1 Company Name J & D TRUCKING INC #15 AU753D						U.S. EPA ID Number NJR000029067				
7. Transporter 2 Company Name:								U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032								U.S. EPA ID Number NJD091291105				
Facility's Phone: 9733441004												
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.e. (D008), 9, PG-III				1		DT	EST. 22	Y	D008	
		2.										
		3.										
		4.										
14. Special Handling Instructions and Additional Information (1) 173083836 - Lead soil/Mar ERG# 171 Chemicals CCN4876												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Officer's Printed/Typed Name MATHEW C. BIANCA ON BEHALF OF USEPA						Signature <i>[Signature]</i>		Month Day Year 4 12 18				
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____											
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name: CLAUDE GMA Signature: <i>[Signature]</i> Month Day Year: 4 12 18 Transporter 2 Printed/Typed Name: _____ Signature: _____ Month Day Year: _____											
DESIGNATED FACILITY	18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Lead: 56520428											
	18b. Alternate Facility (or Generator) Facility's Phone: _____						Manifest Reference Number: _____ U.S. EPA ID Number: _____					
	18c. Signature of Alternate Facility (or Generator) _____						Month Day Year: _____					
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. _____ 3. _____ 4. _____											
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name: Bernice Mills Signature: <i>[Signature]</i> Month Day Year: 4 12 18												

IN



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

83800 LB

07:41 AM 04/12/18

OUT

27200 LB

08:26 AM 04/12/18

WEIGH-TRONIX®



56520
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351280 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC T. # 16 A0754D			U.S. EPA ID Number NJR000028007				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny, NJ 07032 Facility's Phone: 973-344-4004			U.S. EPA ID Number NJ0081281105				
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III	1	DT	EST. 22	Y	D008	
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chemtrac CCN4978							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name MARTIN CRAMA on BEHALF OF USSPA		Signature 		Month 4	Day 12	Year 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name FERNANDO BEC		Signature 		Month 04	Day 12	Year 18	
Transporter 2 Printed/Typed Name		Signature		Month	Day	Year	
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____							
18b. Alternate Facility (or Generator) Facility's Phone: _____				U.S. EPA ID Number			
18c. Signature of Alternate Facility (or Generator)				Month	Day	Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110	2.	3.	4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Bernice Mills		Signature 		Month 11	Day 18	Year 18	



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

81200 LB

07:39 AM 04/12/18

OUT

27340 LB

08:30 AM 04/12/18

WEIGH-TRONIX®



WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263517	2. Page 1 of 1	3. Emergency Response Phone 878-424-8300	4. Manifest Tracking Number 018351281 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2972						
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT 899H NT			U.S. EPA ID Number NJR000020067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD001291105			
Facility's Phone: 9733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST. 22	Y
13. Waste Codes						
14. Special Handling Instructions and Additional Information (1) 173063035 - Lead acid Haz ERG 171 Chemsac CCN4878						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name MARTIN CHAMBERLAIN ON BEHALF OF USEPA			Signature 		Month 4	Day 12
					Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____					
	Transporter signature (for exports only): _____ Date leaving U.S.: _____					
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name Wayne Hartman			Signature 		Month 4
	Transporter 2 Printed/Typed Name			Signature		Day 10
						Year 18
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	Manifest Reference Number: _____					
	18b. Alternate Facility (or Generator)			U.S. EPA ID Number		
	RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL					
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills			Signature 		Month 4	Day 12
					Year 18	



IN

GENERATOR

W2PA

MAN. NO.

018057581 JHK

80280 LB

TRANSPORTER

JTB
019

07:40 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

26780 LB




08:35 AM 04/12/18

WEIGH-TRONIX®



5350

WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817	2. Page 1 of 1	3. Emergency Response Phone 870-424-8300	4. Manifest Tracking Number 018351282 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072								
6. Transporter 1 Company Name J & D TRUCKING INC #15 A0753D					U.S. EPA ID Number NJR009028887			
7. Transporter 2 Company Name					U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032					U.S. EPA ID Number NJD081291105			
Facility's Phone: 8733444004								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-II	1	DT	EST. 22	Y	D008	
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information (1) 173083035 - Lead soil/Haz ERG 171 Chemtrac CCN4876								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Matthew Caccamo on Behalf of USEPA					Signature 		Month Day Year 4 12 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____							
	17. Transporter Acknowledgment of Receipt of Materials							
TRANSPORTER	Transporter 1 Printed/Typed Name CLAUDE GRAY					Signature 		Month Day Year 4 12 18
	Transporter 2 Printed/Typed Name					Signature		Month Day Year
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd: 58160 LBS (58160)							
	18b. Alternate Facility (or Generator)					U.S. EPA ID Number		
	Facility's Phone:					RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL		
	18c. Signature of Alternate Facility (or Generator)					Month Day Year		
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Bernice Mills					Signature 		Month Day Year 4 12 18	

CLEAN EARTH

Faster, smarter, greener solutions...

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

85440 LB

08:40 AM 04/12/18

OUT

27280 LB




08:47 AM 04/12/18

WEIGH-TRONIX®



58160

WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351283JJK					
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032							
Generator's Phone: 973-344-2072										
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000020007							
7. Transporter 2 Company Name			U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD091291105							
Facility's Phone: 9733444094										
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes			
			No.	Type						
	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III		1	DT	EST 22	Y	D008			
	2.									
	3.									
4.										
14. Special Handling Instructions and Additional Information (1) 173083936 - Load solid/haz ERG# 171 Chemical: CCN4978										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generator's/Offendor's Printed/Typed Name MATTHEW CASARSA ON BEHALF OF USEPA			Signature 			Month 4		Day 12	Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:							
	Transporter signature (for exports only):									
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials									
	Transporter 1 Printed/Typed Name Fernando Barr		Signature 			Month 04			Day 12	Year 18
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name		Signature			Month			Day	Year
DESIGNATED FACILITY	18. Discrepancy									
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
	Rec'd: 5632045									
	Manifest Reference Number:									
	18b. Alternate Facility (or Generator) U.S. EPA ID Number									
DESIGNATED FACILITY	Facility's Phone:									
	RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL									
	18c. Signature of Alternate Facility (or Generator) Month Day Year									
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1. H110 2. 3. 4.										
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a										
Printed/Typed Name Bernice Mills			Signature 			Month 4			Day 12	Year 18



CLEAN EARTH

Faster, smarter, greener solutions...

IN

GENERATOR

WCPA

MAN. NO.

01857283

83680 LB

TRANSPORTER

JD

08:46 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

27380 LB

08:55 AM 04/12/18

WEIGH-TRONIX®



50330

WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 890-424-9300	4. Manifest Tracking Number 018351284 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032					
Generator's Phone: 973-344-2072								
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT			U.S. EPA ID Number NJR000026067					
7. Transporter 2 Company Name			U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032			U.S. EPA ID Number NJD001281105					
Facility's Phone: 9733444004								
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
	1. RQ, NA3077, Hazardous waste, solid, n.o.e. (D008), II, PG-II		1	DT	Est. 22	Y	D008	
	2.							
	3.							
4.								
14. Special Handling Instructions and Additional Information (1) 173983836 - Lead acid batz ERQ# 171 Chemical: CCN4876								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offeror's Printed/Typed Name Maria Chana			Signature <i>[Signature]</i>			Month 11	Day 12	Year 18
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name Wayne Harrison			Signature <i>[Signature]</i>			Month 11	Day 10	Year 18
Transporter 2 Printed/Typed Name			Signature			Month	Day	Year
18. Discrepancy								
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Lead 568801B								
Manifest Reference Number:								
18b. Alternate Facility (or Generator) U.S. EPA ID Number								
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Bernice Mills			Signature <i>[Signature]</i>			Month 11	Day 15	Year 18



CLEAN EARTH

Faster, smarter, greener solutions.

IN

GENERATOR

WEPH

MAN. NO.

01851384 fjb

83700 LB

TRANSPORTER

*JHD
019*

08:52 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

26820 LB




08:53 AM 04/12/18

WEIGH-TRONIX®



56880

WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263517	2. Page 1 of 1	3. Emergency Response Phone 878-424-8300	4. Manifest Tracking Number 018351285 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000020007			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD061291105			
Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1	DT	Est 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173083036 - Lead soil/Haz ERG 171 Chemtrac CCN4876							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Matthew Carman on behalf of USEPA					Signature 		Month Day Year 4 12 18
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
	17. Transporter Acknowledgment of Receipt of Materials						
TRANSPORTER	Transporter 1 Printed/Typed Name CTAVID GMA					Signature 	
	Transporter 2 Printed/Typed Name					Signature	
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL					U.S. EPA ID Number	
	Facility's Phone: _____						
	18c. Signature of Alternate Facility (or Generator)					Month Day Year	
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H110	2.	3.	4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Bernice Mills					Signature 	
						Month Day Year 4 15 18	



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:

85840 LB

09:03 AM 04/12/18

OUT




27280 LB

09:13 AM 04/12/18

WEIGH-TRONIX®



58360
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351286 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJ0000029907			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJ0001201105			
Facility's Phone: 8733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III	1	DT	EST-22	Y
13. Waste Codes						
14. Special Handling Instructions and Additional Information: (1) 173083938 - Load with Haz ERG# 171 Chemsac CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name Mariusz Cichanski on behalf of USEPA			Signature 		Month 4	Day 12
					Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____					
	17. Transporter Acknowledgment of Receipt of Materials					
TRANSPORTER	Transporter 1 Printed/Typed Name Fernando Becer			Signature 		Month 04
	Transporter 2 Printed/Typed Name			Signature		Day 12
					Year 18	
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	Manifest Reference Number: _____					
	18b. Alternate Facility (or Generator)			U.S. EPA ID Number		
	Facility's Phone: _____					
18c. Signature of Alternate Facility (or Generator)						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills			Signature 		Month 9	Day 12
					Year 18	



CLEAN EARTH

Faster, smarter, greener solutions...

IN

GENERATOR

W894

MAN. NO.

01835386 JFB

83060 LB

TRANSPORTER

JFB
1/6

09:09 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

27380 LB

09:19 AM 04/12/18

WEIGH-TRONIX®



55680

WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263817	2. Page 1 of 2	3. Emergency Response Phone 800-424-9500	4. Manifest Tracking Number 018351287 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC #1019 AT899HNT				U.S. EPA ID Number NJR000070087			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032 Facility's Phone: 973-344-4604				U.S. EPA ID Number NJ0091291105			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), B, PG-III	1	DT	EST. 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173043936 - Lead acid bat ERG# 171 Chemtrac CCN4876							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offeror's Printed/Typed Name Bernice Mills		Signature Bernice Mills		Month 4		Day 12	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:		Year 18			
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Wayne Hartman		Signature Wayne Hartman		Month 4		Day 12	
Transporter 2 Printed/Typed Name		Signature		Month		Day	
18. Discrepancy		18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Lead: 360304BS		Manifest Reference Number:		U.S. EPA ID Number	
18b. Alternate Facility (or Generator)		Facility's Phone:		Month		Day	
18c. Signature of Alternate Facility (or Generator)		Signature		Year 18			
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a.		Printed/Typed Name Bernice Mills		Signature Bernice Mills		Month 4	
						Day 12	
						Year 18	

IN



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

82800 LB

09:14 AM 04/12/18

OUT




26780 LB

09:21 AM 04/12/18

WEIGH-TRONIX®



52020
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD004263817	2. Page 1 of 1	3. Emergency Response Phone 870-424-8300	4. Manifest Tracking Number 018351288 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #15 AU75317					U.S. EPA ID Number NJR000Q28087	
7. Transporter 2 Company Name					U.S. EPA ID Number	
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032					U.S. EPA ID Number NJD001291105	
Facility's Phone: 9733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-II	1	DT	EST 22	Y
		2.				
		3.				
		4.				
13. Waste Codes D008						
14. Special Handling Instructions and Additional Information (1) 173083935 - Lead acid bat ERG# 171 Chemical CCN4878						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name MATTHEW CRANER ON BEHALF OF USEPA					Signature 	
					Month Day Year 4/12/18	
INTL	16. International Shipments: <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____					
	Transporter signature (for exports only): _____ Date leaving U.S.: _____					
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name CLAUD GRAY					Signature 
					Month Day Year 4/12/18	
Transporter 2 Printed/Typed Name					Signature	
					Month Day Year	
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication: Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	Rec'd 57040 1B3					
	Manifest Reference Number: _____					
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL					
U.S. EPA ID Number						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)						
Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills					Signature 	
					Month Day Year 4/12/18	



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

84300 LB

09:28 AM 04/12/18

OUT

27280 LB

09:42 AM 04/12/18

WEIGH-TRONIX®



57040
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 870-424-9300	4. Manifest Tracking Number 018351289 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000028087			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD001291105			
Facility's Phone: 9733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-II	1	DT	EST 22	Y	D008
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information (1) 1730000000 - Lead acid bat SRCN 171 Chemtrac CCN4878						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name MARTIN CHAMBERLAIN ON BEHALF OF USEPA		Signature 		Month Day Year 4 12 18		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Fernando Becerra		Signature 		Month Day Year 04 12 18		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd: 33730438						
18b. Alternate Facility (or Generator)				Manifest Reference Number: _____ U.S. EPA ID Number		
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator)						Month Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.	H110	2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills		Signature 		Month Day Year 7 15 18		



IN

GENERATOR *W80PA*
MAN. NO. *01851389*
TRANSPORTER *016*
VEHICLE ID:

81100 LB

09:34 AM 04/12/18

DRIVER ON OFF

OUT

REMARKS:

27380 LB

09:44 AM 04/12/18

53720
WEIGHER



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0084263817	2. Page 1 of 1	3. Emergency Response Phone 870-424-8300	4. Manifest Tracking Number 018351290 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NS			U.S. EPA ID Number NJR008028867			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 106 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD081291105			
Facility's Phone: 8733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1 DT	Est 22	Y	D008	
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information (1) 173083035 - Lead acid bat ERG 171 Chemtrac CCN4878						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offendor's Printed/Typed Name MATTHEW CHAMBERLAIN ON BEHALF OF USEPA		Signature 		Month Day Year 11 12 18		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Wayne Hartman		Signature 		Month Day Year 11 12 18		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd: 5/6/80/12						
Manifest Reference Number: _____						
18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills		Signature 		Month Day Year 11 12 18		

IN



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

84460 LB

09:40 AM 04/12/18




OUT

26780 LB

09:50 AM 04/12/18

57680
WEIGHER



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351291 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC # 15 AU753D			U.S. EPA ID Number NJR000028087				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD081291105				
Facility's Phone: 9733441094							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1	DT	Est 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173883835 - Lead acid/baz ERG# 171 Chemtrac CCN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name MATHEW CACAMER ON BEHALF OF USEPA			Signature 		Month Day Year 4/12/18		
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name CLAUD GRAY			Signature 		Month Day Year 4/12/18	
	Transporter 2 Printed/Typed Name			Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input checked="" type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator)			U.S. EPA ID Number			
	Facility's Phone: _____						
	18c. Signature of Alternate Facility (or Generator)			Month Day Year			
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H110	2.	3.	4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest as noted in Item 18a						
	Printed/Typed Name Bernice Mills			Signature 		Month Day Year 4/12/18	


CLEAN EARTH
Faster, smarter, greener solutions...

IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

89460 LB

10:03 AM 04/12/18

OUT

27260 LB

10:18 AM 04/12/18

WEIGH-TRONIX®




WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263B17	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351292 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2072								
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJRO09020067				
7. Transporter 2 Company Name				U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD091291105				
Facility's Phone: 9733444004								
GENERATOR ↓	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-II	1	DT	EST 22	Y	D008	
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information (1) 173083835 - Lead acid bat ERG# 171 Chemtrac CCN4878								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name MARTIN CHAMBERLAIN BEHALF OF USEPA			Signature 			Month Day Year 12 12 18		
INT'L ↓	16. International Shipments: <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
	Transporter signature (for exports only): _____							
TRANSPORTER ↓	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name Fernando Boer			Signature 			Month Day Year 04 12 18	
DESIGNATED FACILITY ↓	Transporter 2 Printed/Typed Name			Signature			Month Day Year	
	18. Discrepancy							
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Rec'd: 51220							
	Manifest Reference Number: _____							
18b. Alternate Facility (or Generator)					U.S. EPA ID Number			
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator)					Month Day Year			
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Bernice Mills				Signature 		Month Day Year 4 12 18		



CLEAN EARTH

Faster, smarter, greener solutions...

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:

WEIGH-TRONIX®



IN

78620 LB




10:05 AM 04/12/18




OUT

27400 LB

10:19 AM 04/12/18

57220
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 970-424-8300		4. Manifest Tracking Number 018351293JJK				
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC #1019 AT 893 HNT		U.S. EPA ID Number NJR000029087										
7. Transporter 2 Company Name		U.S. EPA ID Number										
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032 Facility's Phone: 9733444004		U.S. EPA ID Number NJD061261105										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
						No.	Type					
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III				1	DT	EST 22	Y	D008		
		2.										
		3.										
	4.											
14. Special Handling Instructions and Additional Information (1) 173083036 - Lead acid/baz ERG 171 Chemtrac CCN4876												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offor's Printed/Typed Name MARION CRANER IN BEHALF OF USEPA						Signature 		Month 4	Day 12	Year 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____											
	17. Transporter Acknowledgment of Receipt of Materials											
TRANSPORTER	Transporter 1 Printed/Typed Name Wayne Harrison						Signature 		Month 4	Day 12	Year 18	
	Transporter 2 Printed/Typed Name						Signature		Month	Day	Year	
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd. 35600 lbs											
	Manifest Reference Number:											
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number											
	Facility's Phone:											
	18c. Signature of Alternate Facility (or Generator)								Month	Day	Year	
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
	1. H110		2.		3.		4.					
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
	Printed/Typed Name Bernice Mills						Signature 		Month 4	Day 12	Year 18	

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817	2. Page 1 of 1	3. Emergency Response Phone 890-424-8300	4. Manifest Tracking Number 018351294 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #15 AU753D			U.S. EPA ID Number NJR000028867			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD081291105			
Facility's Phone: 9733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, acid, n.o.s. (D008), 2, PG-II	1	DT	EST 22	Y
13. Waste Codes D008						
14. Special Handling Instructions and Additional Information (1) 173082838 - Lead acid Haz ERG# 171 Chemical CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name MARION CHANCE as Beneficiary USEPA			Signature 		Month 4	Day 12
					Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____					
	17. Transporter Acknowledgment of Receipt of Materials					
TRANSPORTER	Transporter 1 Printed/Typed Name CLAUDE GRAY			Signature 		Month 4
						Day 12
Transporter 2 Printed/Typed Name			Signature		Month	Day
					Year	
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	100% of 55480 LBS					
	Manifest Reference Number: _____					
	18b. Alternate Facility (or Generator) U.S. EPA ID Number					
RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL						
Facility's Phone: _____						
18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2. _____		3. _____		4. _____
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills			Signature 		Month 4	Day 12
					Year 18	



GENERATOR *US EPA*
MAN. NO. *018551243*
TRANSPORTER *JAD*
VEHICLE ID. *0019*
DRIVER ON OFF
REMARKS:

82440 LB

10:15 AM 04/12/18

OUT

26780 LB

10:25 AM 04/12/18



35640
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJDD014263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351294 JJK
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072					
6. Transporter 1 Company Name J & D TRUCKING INC #15 AU753D		U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name		U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		U.S. EPA ID Number NJ0991291105			
Facility's Phone: 973344-4004					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III	1 1 DT		EST 22 Y
		2.			
		3.			
		4.			
13. Waste Codes D008					
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG# 171 Chemtrac CCN4876					
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.					
Generator's/Offlor's Printed/Typed Name Matthew Caramia on BEHALF OF USSON		Signature 		Month Day Year 4/12/18	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____				
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name CLAUDE GRAY Signature Claude Gray Month Day Year 4/12/18				
	Transporter 2 Printed/Typed Name Signature Month Day Year				
DESIGNATED FACILITY	18. Discrepancy 18a. Discrepancy Indicator/Space Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Quantity 55480000 Manifest Reference Number: _____				
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number				
	Facility's Phone: _____				
	18c. Signature of Alternate Facility (or Generator) Month Day Year				
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. 3. 4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Bernice Mills Signature Bernice Mills Month Day Year 4/12/18					



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:

82760 LB

10:31 AM 04/12/18

OUT





27280 LB

10:39 AM 04/12/18

WEIGH-TRONIX®



548
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351295 JJK				
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032						
Generator's Phone: 973-344-2072									
6. Transporter 1 Company Name J & D TRUCKING INC				U.S. EPA ID Number NJR000020067					
7. Transporter 2 Company Name				U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD091261105					
Facility's Phone: 9733444004									
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
	X	1. RQ, NA3077, Hazardous waste, acid, n.o.s. (D008), 2, PG-II	1	DT	EST 22	Y	D008		
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information (1) 173063030 - Lead acid/Haz ERG 171 (Chemical: CCN4876									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offoror's Printed/Typed Name KIM TIN CHAN				Signature 		Month 11	Day 12	Year 18	
INT'L	16. International Shipments: <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____								
	Transporter signature (for exports only): _____								
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Fernando Becerra				Signature 		Month 04	Day 12	Year 18
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name				Signature		Month	Day	Year
	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection				Manifest Reference Number: _____				
	18b. Alternate Facility (or Generator)				U.S. EPA ID Number				
	Facility's Phone: _____								
DESIGNATED FACILITY	18c. Signature of Alternate Facility (or Generator)				Signature 		Month 4	Day 15	Year 18
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
	1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
Printed/Typed Name Bernice Mills				Signature 		Month 4	Day 15	Year 18	



IN

GENERATOR

USPA

MAN. NO.

01835132577B

TRANSPORTER

JHD

78620 LB

VEHICLE ID.

10:37 AM 04/12/18

DRIVER ON

OFF

OUT

REMARKS:

27400 LB

10:48 AM 04/12/18

WEIGH-TRONIX®



51320
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351296 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT			U.S. EPA ID Number NJR000020067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032			U.S. EPA ID Number NJD091201105			
Facility's Phone: 9733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y
		2.				
		3.				
		4.				
13. Waste Codes						
14. Special Handling Instructions and Additional Information (1) 173083936 - Lead soil/Haz ERG# 171 Chemical CCN4976						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offeror's Printed/Typed Name Sam Yin Chan			Signature <i>[Signature]</i>		Month 4	Day 12
					Year 18	
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____					
	Transporter signature (for exports only): _____					
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name Wayne Harrison			Signature <i>[Signature]</i>		Month 4
					Year 18	
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd 35720 lbs					
18b. Alternate Facility (or Generator)			Manifest Reference Number:		U.S. EPA ID Number	
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)					Month	Day
					Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills			Signature <i>[Signature]</i>		Month 4	Day 12
					Year 18	



IN

GENERATOR

W229A

MAN. NO.

018351296 JH

82500 LB

TRANSPORTER

JH
019

10:43 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

26780 LB

10:57 AM 04/12/18

WEIGH-TRONIX®



55720
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351297 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC			U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD091291105			
Facility's Phone: 9733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	22	Y	D008
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information (1) 173003936 - Lead acid-baz ERG# 171 Chemtrec CCN4878						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offoror's Printed/Typed Name ROMI HO CHAN		Signature <i>[Signature]</i>		Month 11	Day 12	Year 18
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Transporter signature (for exports only): Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name CLAUD GRAY		Signature <i>[Signature]</i>		Month 4	Day 12	Year 18
Transporter 2 Printed/Typed Name		Signature		Month	Day	Year
18. Discrepancy						
18a. Discrepancy Indication Space Rec'd 5/23/2018		<input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type		<input type="checkbox"/> Residue	<input type="checkbox"/> Partial Rejection	<input type="checkbox"/> Full Rejection
18b. Alternate Facility (or Generator)		Manifest Reference Number:		U.S. EPA ID Number		
Facility's Phone:		RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL				
18c. Signature of Alternate Facility (or Generator)				Month	Day	Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.	H110	2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name: Bernice Mills		Signature <i>[Signature]</i>		Month 7	Day 15	Year 18



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

83540 LB

10:52 AM 04/12/18




OUT

27260 LB

11:12 AM 04/12/18



56280
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1	3. Emergency Response Phone 870-424-9300		4. Manifest Tracking Number 018351298 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032					Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032					
Generator's Phone: 973-344-2072										
6. Transporter 1 Company Name J & D TRUCKING INC					U.S. EPA ID Number NJR000026067					
7. Transporter 2 Company Name					U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032					U.S. EPA ID Number NJD991291105					
Facility's Phone: 9733444004										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
					No.	Type				
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-II			1	DT	EST 22	Y	D008	
		2.								
		3.								
		4.								
14. Special Handling Instructions and Additional Information (1) 173083835 - Lead soil/Haz ERG# 171 Chemical CCN4876										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generators/Offeror's Printed/Typed Name Kam Yin Chan					Signature 		Month 11	Day 12	Year 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____									
	Transporter signature (for exports only): _____									
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials									
	Transporter 1 Printed/Typed Name Fernando Bocell					Signature 		Month 09	Day 12	Year 18
	Transporter 2 Printed/Typed Name					Signature		Month	Day	Year
DESIGNATED FACILITY	18. Discrepancy									
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
	Rec'd: 52600 lbs									
	Manifest Reference Number: _____									
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number									
	Facility's Phone: _____									
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____									
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
	1. H110	2.	3.	4.						
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a									
	Printed/Typed Name Bernice Mills					Signature 		Month 11	Day 15	Year 18



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

84000 LB

11:03 AM 04/12/18

OUT

27400 LB

11:19 AM 04/12/18



57600
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351299 JJK			
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			
6. Transporter 1 Company Name J & D TRUCKING INC #1019 AT899H NJ		Generator's Phone: 973-344-2072						U.S. EPA ID Number NJR000020007			
7. Transporter 2 Company Name								U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Keamy NJ 07032		Facility's Phone: 9733444004						U.S. EPA ID Number NJD091201105			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
						No.	Type				
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-II				1	DT	EST 22	Y	D008	
		2.									
		3.									
	4.										
14. Special Handling Instructions and Additional Information (1) 173083035 - Lead soil/Haz ER01171 Chemtrac CCN4878											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offor's Printed/Typed Name Ron Yin Chan Signature [Signature] Month 4 Day 12 Year 18											
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:										
	Transporter signature (for exports only):										
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials										
	Transporter 1 Printed/Typed Name Wayne Hartman Signature [Signature] Month 4 Day 12 Year 18										
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name Signature Month Day Year										
	18. Discrepancy /										
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection										
	Manifest Reference Number:										
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number										
Facility's Phone:											
18c. Signature of Alternate Facility (or Generator) Month Day Year											
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
1. H110		2.		3.		4.					
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
Printed/Typed Name Bernice Mills Signature [Signature] Month 4 Day 12 Year 18											



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

82220 LB

11:09 AM 04/12/18

OUT

26740 LB

11:20 AM 04/12/18



35480
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263017	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351300 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC # 15 AU753D			U.S. EPA ID Number NJR000020067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD091291105			
Facility's Phone: 9733444004						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-II	1	DT	EST 22	Y
		2.				
		3.				
	4.					
13. Waste Codes						
14. Special Handling Instructions and Additional Information (1) 173083936 - Lead soil/Haz ERG# 171 Chemtrec CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offoror's Printed/Typed Name Kam Yin Chan			Signature K Y Chan		Month 4	Day 12 Year 18
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____					
	Transporter signature (for exports only): _____					
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials					
	Transporter 1 Printed/Typed Name CIAUD GUY			Signature Clayton Gray		Month 4 Day 12 Year 18
	Transporter 2 Printed/Typed Name			Signature		Month Day Year
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	Rec'd: 55840188					
	18b. Alternate Facility (or Generator)			Manifest Reference Number		
	Facility's Phone:			U.S. EPA ID Number		
	18c. Signature of Alternate Facility (or Generator)			Month Day Year		
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
	1. H110	2.	3.	4.		
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a					
	Printed/Typed Name Bernice Mills			Signature Bernice Mills		Month 4 Day 12 Year 18



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

83100 LB

11:26 AM 04/12/18

OUT

27260 LB

11:36 AM 04/12/18

WEIGHER

WEIGH-TRONIX®



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263B17		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351301 JJK							
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032							
6. Transporter 1 Company Name J & D TRUCKING INC		U.S. EPA ID Number NJR000029087													
7. Transporter 2 Company Name		U.S. EPA ID Number													
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		U.S. EPA ID Number NJD091291105													
Facility's Phone: 9733444004															
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes					
						No.	Type								
	X	1. RQ, NA3077, Hazardous waste, acid, n.o.s. (D008), 8, PG-II				1	DT	EST 22	Y	D008					
		2.													
		3.													
	4.														
14. Special Handling Instructions and Additional Information (1) 173053838 - Lead acid/Haz ERG# 171 Chemtrec CCN4976															
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Offor's Printed/Typed Name Kam Tin Chan Signature K. J. Chan Month 9 Day 12 Year 18															
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____														
	Transporter signature (for exports only): _____														
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials														
	Transporter 1 Printed/Typed Name Fernando Baez Signature _____ Month 09 Day 12 Year 18														
	Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____														
DESIGNATED FACILITY	18. Discrepancy														
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection														
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL Manifest Reference Number: _____ U.S. EPA ID Number _____														
	Facility's Phone: _____														
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____														
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)															
1. H110				2. _____				3. _____				4. _____			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a															
Printed/Typed Name Bernice Mills Signature Bernice Mills Month 4 Day 13 Year 17															



IN

GENERATOR *W8PA*
MAN. NO. *018351301*
TRANSPORTER *HD*
VEHICLE ID. *016*

84060 LB

11:34 AM 04/12/18

DRIVER ON OFF

OUT

REMARKS:

27380 LB

11:46 AM 04/12/18



57680
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351302 JJK	
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072		6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899HNT				U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name						U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave, Kearny NJ 07032						U.S. EPA ID Number NJD081201105			
Facility's Phone: 9733444004									
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
					No.	Type			
	X	1. RQ, NA3077, Hazardous waste, acid, n.o.s. (D008), 8, PG-II			1	DT	ESI 22	Y	D008
		2.							
		3.							
	4.								
14. Special Handling Instructions and Additional Information (1) 173083038 - Lead acid bat EROW 171 Chemtrac CCN4878									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Karl Friedman					Signature [Signature]		Month 9 Day 12 Year 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____								
	Transporter signature (for exports only): _____								
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Wayne Hartman					Signature [Signature]		Month 9 Day 10 Year 18	
	Transporter 2 Printed/Typed Name					Signature		Month Day Year	
DESIGNATED FACILITY	18. Discrepancy								
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	Manifest Reference Number: _____								
	18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____								
	Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year								
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
	1. H110	2.	3.	4.					
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
	Printed/Typed Name Bernice Mills					Signature [Signature]		Month 9 Day 12 Year 18	



CLEAN EARTH

Faster, smarter, greener solutions...

IN

GENERATOR

U20PA

MAN. NO.

0183513081119

82500 LB

TRANSPORTER

019

11:37 AM 04/12/18

VEHICLE ID.

DRIVER ON

OFF

OUT

REMARKS:

26780 LB

11:52 AM 04/12/18

WEIGH-TRONIX®



55740
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351306 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave. Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave. Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC #15 A0753D				U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032				U.S. EPA ID Number NJD081281105			
Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), R, PG-III	1	DT	Fast 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173093938 - Lead sol/Haz ERG 171 Chemtrec CCN4876							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name Karl Yin Chan			Signature [Signature]		Month 6 Day 12 Year 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name CLAUDE GRAY			Signature [Signature]		Month 4 Day 12 Year 18	
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name			Signature		Month Day Year	
	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator)			U.S. EPA ID Number			
Facility's Phone: _____			RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL				
18c. Signature of Alternate Facility (or Generator)							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Bernice Mills			Signature [Signature]		Month 7 Day 13 Year 18		



IN

GENERATOR *USPA*
MAN. NO. *01831306 JH*
TRANSPORTER *015*
VEHICLE ID.
DRIVER ON OFF
REMARKS:

85420 LB

11:50 AM 04/12/18

OUT

27280 LB

12:02 PM 04/12/18



38140
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351307 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032 Generator's Phone: 973-344-2072			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
6. Transporter 1 Company Name J & D TRUCKING INC T-# 16 AU7510			U.S. EPA ID Number NJR000028067					
7. Transporter 2 Company Name			U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032 Facility's Phone: 9733444004			U.S. EPA ID Number NJD001261105					
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), II, PG-II		1 DT		EST 22	Y	D008	
	2.							
	3.							
	4.							
14. Special Handling Instructions and Additional Information (1) 173083030 - Lead soil/Haz ERG# 171 Chemtrac CCN4976								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Kam Yin Chan			Signature [Signature]			Month 4	Day 12	Year 18
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Transporter signature (for exports only): Date leaving U.S.:								
17. Transporter Acknowledgment of Receipt of Materials								
Transporter 1 Printed/Typed Name Fernando Barz			Signature [Signature]			Month 04	Day 12	Year 18
Transporter 2 Printed/Typed Name			Signature			Month	Day	Year
18. Discrepancy								
18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection 1000 d. 53000								
Manifest Reference Number:								
18b. Alternate Facility (or Generator)			U.S. EPA ID Number					
Facility's Phone:								
18c. Signature of Alternate Facility (or Generator)						Month	Day	Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Bernice Mills			Signature [Signature]			Month 11	Day 15	Year 18



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

79380 LB

11:59 AM 04/12/18

OUT

27380 LB

12:08 PM 04/12/18



52600
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD004263817	2. Page 1 of 1	3. Emergency Response Phone 800-474-8300	4. Manifest Tracking Number 018351308 JJK	
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
Generator's Phone: 973-344-2072						
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NJ			U.S. EPA ID Number NJR008020067			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD001281105			
Facility's Phone: 9733444004						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	1. RG, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III		1	DT	EST ZZ	Y
	2.					
	3.					
4.						
13. Waste Codes						
D008						
14. Special Handling Instructions and Additional Information (1) 173063935 - Lead soil/Haz ERG# 171 Chemtrac CCN4876						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name Kain Yin Chon			Signature <i>[Signature]</i>		Month 4	Day 12
					Year 18	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Wayne Hartman			Signature <i>[Signature]</i>		Month 4	Day 12
					Year 18	
Transporter 2 Printed/Typed Name			Signature		Month	Day
					Year	
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Rec'd: 5/4/18						
18b. Alternate Facility (or Generator)			Manifest Reference Number:		U.S. EPA ID Number	
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)					Month	Day
					Year	
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H110		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name Bernice Mills			Signature <i>[Signature]</i>		Month 4	Day 12
					Year 18	



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:

81500 LB

12:52 PM 04/12/18

OUT

26760 LB

01:00 PM 04/12/18



59740
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351309 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC #15-AU75312			U.S. EPA ID Number NJR000029667				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032			U.S. EPA ID Number NJD001261105				
Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit WL/Vol.	
			No.	Type			
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	22	Y	
14. Special Handling Instructions and Additional Information (1) 173063938 - Lead acid/Haz ERG# 171 Chemtrec CCN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offeror's Printed/Typed Name Sam Yin Chan			Signature <i>[Signature]</i>		Month 4	Day 12	
					Year 18		
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name CLAUDE GRAY			Signature <i>[Signature]</i>		Month 4	Day 12
						Year 18	
	Transporter 2 Printed/Typed Name			Signature		Month	Day
						Year	
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Rec'd: 5866012						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____						
	Facility's Phone: _____						
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____						
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H110	2. _____	3. _____	4. _____			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Bernice Mills			Signature <i>[Signature]</i>		Month 4	Day 12
						Year 18	



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

05700 LB

12:58 PM 04/12/18

OUT

27040 LB

01:08 PM 04/12/18

WEIGH-TRONIX®



58660
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263B17		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351310 JJK			
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			
6. Transporter 1 Company Name J & D TRUCKING INC		Generator's Phone: 973-344-2072						U.S. EPA ID Number NJR000028067			
7. Transporter 2 Company Name								U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032		Facility's Phone: 8733444004						U.S. EPA ID Number NJD081281105			
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
						No.	Type				
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-II				1	DT	EST 22	Y	D008	
		2.									
		3.									
		4.									
14. Special Handling Instructions and Additional Information (1) 173063938 - Lead acid/baz ERG# 171 Chemtrec CCN4878											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offeror's Printed/Typed Name San Tin Chan						Signature <i>[Signature]</i>		Month Day Year 4/12/18			
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____										
	17. Transporter Acknowledgment of Receipt of Materials										
	Transporter 1 Printed/Typed Name Fernando Barr						Signature <i>[Signature]</i>		Month Day Year 10/12/18		
TRANSPORTER	Transporter 2 Printed/Typed Name						Signature		Month Day Year		
	18. Discrepancy										
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd: 53300485 Manifest Reference Number: _____										
DESIGNATED FACILITY	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____										
	Facility's Phone: _____										
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year										
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
1. H110				2.				3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
Printed/Typed Name Bernice Mills						Signature <i>[Signature]</i>		Month Day Year 7/3/18			



IN

GENERATOR *W2PA*
MAN. NO. *0183310 JH*
TRANSPORTER *JH*
VEHICLE ID. *76*

80440 LB

01:02 PM 04/12/18

DRIVER ON OFF

OUT

REMARKS:




27220 LB

01:12 PM 04/12/18

53220
WEIGHER

WEIGH-TRONIX®



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-9300	4. Manifest Tracking Number 018351311 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT				U.S. EPA ID Number NJR000029067			
7. Transporter 2 Company Name				U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032			U.S. EPA ID Number NJD001281105				
Facility's Phone: 8733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information (1) 173063936 - Lead acid/Haz ERG# 171 Chemical: CCN4976							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offeror's Printed/Typed Name Ram Y. Chan				Signature 		Month Day Year 21 12 18	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Wayne Hawthorn				Signature 		Month Day Year 4 18
	Transporter 2 Printed/Typed Name				Signature		Month Day Year
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Rec'd 53600 LBS						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator)				U.S. EPA ID Number		
	Facility's Phone: _____						
	18c. Signature of Alternate Facility (or Generator)						Month Day Year
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H110	2.	3.	4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Bernice Mills				Signature 		Month Day Year 7 12 18



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

79180 LB

01:14 PM 04/12/18

OUT

26580 LB

01:28 PM 04/12/18

WEIGH-TRONIX®



52600
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064263017	2. Page 1 of 1	3. Emergency Response Phone 800-424-9333	4. Manifest Tracking Number 018864781 JJK						
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032									
Generator's Phone: 973-344-2072											
6. Transporter 1 Company Name J & D TRUCKING INC #1019 AT299H NT		U.S. EPA ID Number NJR000029067									
7. Transporter 2 Company Name		U.S. EPA ID Number									
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy N.J. 07032		U.S. EPA ID Number NJ0901201105									
Facility's Phone: 8733444004											
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes				
			No.	Type							
	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-III		1	DT	22 EG	T	D008				
	2.										
	3.										
4.											
14. Special Handling Instructions and Additional Information (1) 173083938 - Lead soil/Haz ERG #171 (48 CFR 172.604(b)) Order#: 210215 - Note:											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offor's Printed/Typed Name Sam Yin Chan		Signature [Signature]		Month 4		Day 13		Year 18			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:									
17. Transporter Acknowledgment of Receipt of Materials		Transporter 1 Printed/Typed Name Wayne Hantman		Signature [Signature]		Month 4		Day 13		Year 18	
Transporter 2 Printed/Typed Name		Signature		Month		Day		Year			
18. Discrepancy											
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection											
18b. Alternate Facility (or Generator)		Manifest Reference Number:		U.S. EPA ID Number							
Facility's Phone:		RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL									
18c. Signature of Alternate Facility (or Generator)		Month		Day		Year					
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
1. H110		2.		3.		4.					
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
Printed/Typed Name Bernice Mills		Signature [Signature]		Month 7		Day 13		Year 18			



IN

GENERATOR

USE PA

MAN. NO.

018864781111B

80560 LB

TRANSPORTER

JRD
019

11:15 AM 04/13/18

VEHICLE ID.

DRIVER ON OFF

OUT

REMARKS:

26820 LB

11:24 AM 04/13/18



53740
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJ0064268817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018864782 JJK	
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			
6. Transporter 1 Company Name J & D TRUCKING INC #019 A789911 NT		U.S. EPA ID Number NJR000028967		7. Transporter 2 Company Name		U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny, NJ 07032		U.S. EPA ID Number NJ0901201105		Facility's Phone: 973-444-0004					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
					No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III			1	DT	EST 22	T	D008
		2.							
		3.							
		4.							
14. Special Handling Instructions and Additional Information (1) 173083838 - Lead soil/Haz ERG #171 (49 CFR 172.604(b)) <div style="text-align: right;">Order#: 210216 - Note:</div>									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offero's Printed/Typed Name Kam Yin Chan					Signature 		Month Day Year 4/13/18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____								
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name NAYAR HARTMAN Signature Month Day Year 4/13/18 Transporter 2 Printed/Typed Name Signature Month Day Year								
TRANSPORTER	18. Discrepancy 18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____ 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: _____ 18c. Signature of Alternate Facility (or Generator) Month Day Year								
	RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL								
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. 3. 4.								
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Bernice Mills Signature Month Day Year 4/13/18								
DESIGNATED FACILITY									



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:



IN

81660 LB




11:44 AM 04/13/18

OUT

26540 LB

12:00 PM 04/13/18

55120
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351312 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT			U.S. EPA ID Number NJR000020067				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny, NJ 07032			U.S. EPA ID Number NJD081281105				
Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	
			No.	Type			
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-II	1	DT	Est. 22	Y	
		2.					
		3.					
	4.						
13. Waste Codes							
14. Special Handling Instructions and Additional Information (1) 173063938 - Lead acid/Haz ERG# 171 Chemical CCN4876							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Kam Yin Chan			Signature 		Month 4	Day 13	
					Year 18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Wayne Hartman			Signature 		Month 4	Day 13
	Transporter 2 Printed/Typed Name			Signature		Month	Day
						Year	
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Lead - 51900000						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____						
	Facility's Phone: _____						
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____						
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H110	2.	3.	4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Bernice Mills			Signature 		Month 1	Day 15
						Year 18	



CLEAN EARTH

Faster, smarter, greener solutions...

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

WEIGH-TRONIX®



IN

78660 LB




07:31 AM 04/13/18

OUT

26760 LB

08:29 AM 04/13/18

51900
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817	2. Page 1 of 1	3. Emergency Response Phone 856-424-8300	4. Manifest Tracking Number 018351313 JJK			
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032					
Generator's Phone: 973-344-2072								
6. Transporter 1-Company Name J & D TRUCKING INC #019 AT899H NT			U.S. EPA ID Number NJR000020067					
7. Transporter 2 Company Name			U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032			U.S. EPA ID Number NJD991291105					
Facility's Phone: 973444004								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 2, PG-III	1	DT	Est 22	Y	D008	
		2.						
		3.						
		4.						
14. Special Handling Instructions and Additional Information (1) 173063038 - Lead acid Max ERQ# 171 Chemrec CCN4878								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Kim Yin Chan			Signature 		Month 9	Day 13	Year 18	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____							
	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name Wayne Hantman		Signature 		Month 4	Day 13	Year 18	
Transporter 2 Printed/Typed Name		Signature		Month	Day	Year		
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Manifest Reference Number: _____							
	18b. Alternate Facility (or Generator)				U.S. EPA ID Number			
	Facility's Phone: _____							
18c. Signature of Alternate Facility (or Generator)								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H110		2.		3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Bernice Mills				Signature 		Month 11	Day 13	Year 18

IN



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON OFF

REMARKS:

82420 LB

08:48 AM 04/13/18

OUT

26780 LB

09:00 AM 04/13/18



53640
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD084263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351314 JJK				
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032				
6. Transporter 1 Company Name J & D TRUCKING INC #1019 AT899H NT		Generator's Phone: 973-344-2072						U.S. EPA ID Number NJR000020067				
7. Transporter 2 Company Name								U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave Kearny NJ 07032		Facility's Phone: 9733444004						U.S. EPA ID Number NJD001291105				
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
	X	1. RC, NA3077, Hazardous waste, solid, n.o.s. (D008), 3, PG-II				1	DT	EST 22	Y	D008		
		2.										
		3.										
		4.										
14. Special Handling Instructions and Additional Information (1) 173083038 - Lead acid/Haz ERG# 171 Chemtrec CCN4878												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offoror's Printed/Typed Name Ken Yin Chan						Signature <i>[Signature]</i>		Month Day Year 4/13/18				
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____											
	17. Transporter Acknowledgment of Receipt of Materials											
TRANSPORTER	Transporter 1 Printed/Typed Name Wayne HANTEMAN						Signature <i>[Signature]</i>		Month Day Year 4/13/18			
	Transporter 2 Printed/Typed Name						Signature		Month Day Year			
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd. 52400038											
	Manifest Reference Number: _____											
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____											
	Facility's Phone: _____											
18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____												
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)												
1. H110				2.				3.		4.		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a												
Printed/Typed Name Bernice Mills						Signature <i>[Signature]</i>		Month Day Year 4/13/18				



IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

79160 LB

09:27 AM 04/13/18

OUT

26760 LB

09:36 AM 04/13/18



52410
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263517	2. Page 1 of 1	3. Emergency Response Phone 800-424-8300	4. Manifest Tracking Number 018351315 JJK		
5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032			Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Keamy, NJ 07032				
Generator's Phone: 973-344-2072							
6. Transporter 1 Company Name J & D TRUCKING INC #019 A+899 HNT			U.S. EPA ID Number NJR000029067				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Keamy NJ 07032			U.S. EPA ID Number NJD091281105				
Facility's Phone: 973444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 9, PG-III	1	DT	EST 22	Y	D008
14. Special Handling Instructions and Additional Information (1) 173063830 - Lead soil/Haz ERG# 171 Chemical CCN4878							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offoror's Printed/Typed Name US ARMY CORPS OF ENGINEERS ON BEHALF OF USEPA			Signature <i>[Signature]</i>		Month Day Year 4/13/18		
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
	Transporter signature (for exports only): _____						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Wayne HANTMAN			Signature <i>[Signature]</i>		Month Day Year 4/13/18	
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name			Signature		Month Day Year	
	18. Discrepancy						
	18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number: _____						
	18b. Alternate Facility (or Generator)			U.S. EPA ID Number			
Facility's Phone: _____			RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL				
18c. Signature of Alternate Facility (or Generator)							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Bernice Mills			Signature <i>[Signature]</i>		Month Day Year 4/13/18		



CLEAN EARTH

Faster, smarter, greener solutions...

IN

GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

82540 LB

09:51 AM 04/13/18

OUT

26740 LB

10:07 AM 04/13/18

WEIGH-TRONIX®



5880
WEIGHER

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8900		4. Manifest Tracking Number 018351316 JJK			
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032		Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032							
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT		U.S. EPA ID Number NJR000020087		7. Transporter 2 Company Name		U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		U.S. EPA ID Number NJD991291105		Facility's Phone: 9733444004							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (D008), 8, PG-II				1	DT	FST 22	Y	D008	
		2.									
		3.									
		4.									
14. Special Handling Instructions and Additional Information (1) 173063938 - Lead soil/Haz ERG# 171 Chemtrac CCN4876											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offeror's Printed/Typed Name Kam Yin Chan Signature [Signature] Month 4 Day 13 Year 18											
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____										
	17. Transporter Acknowledgment of Receipt of Materials Transporter signature (for exports only): _____										
TRANSPORTER	Transporter 1 Printed/Typed Name Wayne Hartman Signature [Signature] Month 4 Day 13 Year 18										
	Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____										
DESIGNATED FACILITY	18. Discrepancy 18a. Discrepancy Indication Space <input checked="" type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Lead 55960488 Manifest Reference Number: _____										
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____										
	Facility's Phone: _____										
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____										
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H110 2. _____ 3. _____ 4. _____										
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Bernice Mills Signature [Signature] Month 4 Day 13 Year 18											

IN



GENERATOR

MAN. NO.

TRANSPORTER

VEHICLE ID.

DRIVER ON

OFF

REMARKS:

84740 LB

10:25 AM 04/13/18

OUT

26780 LB

10:32 AM 04/13/18

57960
WEIGHER



UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD064263817		2. Page 1 of 1		3. Emergency Response Phone 800-424-8300		4. Manifest Tracking Number 018351317 JJK							
		5. Generator's Name and Mailing Address USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032						Generator's Site Address (if different than mailing address) USEPA Region 2 77 Jacobus Ave Kearny, NJ 07032							
6. Transporter 1 Company Name J & D TRUCKING INC #019 AT899H NT		Generator's Phone: 973-344-2072						U.S. EPA ID Number NJR008029087							
7. Transporter 2 Company Name								U.S. EPA ID Number							
8. Designated Facility Name and Site Address Clean Earth of North Jersey 105 Jacobus Ave. Kearny NJ 07032		Facility's Phone: 973-344-4094						U.S. EPA ID Number NJD991291105							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes					
						No.	Type								
	X	1. RQ, NA3077, Hazardous waste, acid, n.o.s. (D008), 8, PG-II				1	DT	EST 22	Y	D008					
		2.													
		3.													
	4.														
14. Special Handling Instructions and Additional Information (1) 17993939 - Lead acid/Haz ERG# 171 Chemtrac CCN4878															
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Offeror's Printed/Typed Name Kim Vinchan Signature Kim Vinchan Month 4 Day 13 Year 18															
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____														
	17. Transporter Acknowledgment of Receipt of Materials														
TRANSPORTER	Transporter 1 Printed/Typed Name Wayne Hartman Signature Wayne Hartman Month 4 Day 13 Year 18														
	Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____														
DESIGNATED FACILITY	18. Discrepancy														
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Rec'd: 34/00/00 Manifest Reference Number: _____														
	18b. Alternate Facility (or Generator) RECEIVED PENDING MANIFEST REVIEW AND QUALITY CONTROL U.S. EPA ID Number _____														
	Facility's Phone: _____														
18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____															
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)															
1. H110				2. _____				3. _____				4. _____			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a															
Printed/Typed Name Bernice Mills Signature Bernice Mills Month 4 Day 13 Year 18															



IN

GENERATOR *U280A*
MAN. NO. *018351317*
TRANSPORTER *J&D*
VEHICLE ID. *019*

80820 LB

10:50 AM 04/13/18

DRIVER ON OFF

OUT

REMARKS:

26720 LB

11:01 AM 04/13/18



54100
WEIGHER